ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
5

Ward Name
Jakkuru

Street ID
W2015, W1118, W1114, W0924, W1619, W1621, W1617, W

Street Name
1st Main Rd 10th Crs Bank Avenue Horamavu, 1st Crs, NA, 2nd Crs

Significant Landmark
CHOKKANAHALLI VILLAGE LIMITS

Segment No.
5/C-W2015/S012732

Total Length (m)
389.07

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	117.93	77.632730	13.079189	77.633807	13.079037	W1615	RI-A07
2	76.61	77.632852	13.076220	77.633557	13.076172	W2015	RI-A07
3	194.53	77.632543	13.074704	77.632855	13.076436	W1108	W2017

Work Details

History of Road / Lane / Circles

Name of the Work
Construction of Burial Ground Compound Wall (Balance Work) at Sampigehalli in ward no 05 Byatarayanapura Sub-Division Yelahanka zon

Sanctioned Estimated Amount (Rs.)
3000000

Sanctioned Year
2014

Year
2014 - 2015

Type of Work
Drain Maintenance

Other Work Type

Tender
Tender

Work Details
Construction of Burial Ground Compound Wall (Balance Work) at Sampigehalli in ward no 05 Byatarayanapura Sub-Division Yelahanka zon

Job No. / Work Code
005-14-000053

Work Order No.
EE/BTP/BBMP/E-TND/351/2014-15

Work Order Date
23/03/2015

Period of Extention
60 DAYS

Defect Liability Period From
23/03/2015

Defect Liability Period To
22/03/2016

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor
S.K.KESHAVAMURTHY

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)
0.00

Phone No.

E-Mail ID

9902126909

Field Inspection Details

Number of Trees	Any Other Information	Name
12		CHANDRAKANTHA
Date of Inspection	**Remarks**	
19/07/2016	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W2015, W1118, W1114, W0924,

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	19/07/2016	18/08/2016	COMPLETED
SE	VASU K M	19/07/2016	18/08/2016	COMPLETED
EE	YARAPPA REDDY	19/07/2016	18/08/2016	COMPLETED
AEE	J N LOKESH	19/07/2016	18/08/2016	COMPLETED
AE	CHANDRAKANTH	19/07/2016	18/08/2016	COMPLETED
AE	CHANDRAKANTH	19/07/2016	18/08/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W2015, W1118, W1114, W0924,